

[2025] No.0013 | Release Notes

Issued: April 29, 2025

Subject: i83 Firmware 1.3.11.2

Region: International

1. Requirements

This firmware version includes fixes and enhancements to the i83 series GNSS receiver firmware.

Note: Upgrading from the previous firmware version 1.3.10 of the i83 series GNSS receiver to version 1.3.11.2 is recommended.

2. Supported GNSS Receivers

The following table identifies the GNSS receivers supported by this revision:

Part Number	Description
A19318980901070002	I83 GNSS

3. Version 1.3.11.2 Release Note

The release note describes the new features, improvements and bug fixed for the i83 series GNSS receiver firmware.

Optimize	Description	Type
Screen display	Updated compatibility with new screens.	Improvements

Note: Before updating the receiver, any files and data on the receiver must be backed up.

4. Loading the new Firmware

The new firmware can be download at:

https://chcnavigation.jianguoyun.com/p/DYbqJy0Qtg_UCxjolfoFIAA

Note: Follow the firmware update instructions provided by CHC Navigation.

5. Additional Information

For more information about this change, please contact support@chcnavigation.com
CHC Navigation Support Team